
Licensing Inspection Report (Annual Inspection)

Facility: R K MACDONALD NURSING HOME
CORPORATION

Address: 64 PLEASANT ST.
ANTIGONISH NS, B2G 1W7

Date(s) of Inspection: March 23, 2022

Requirements resulting from licensing inspection:

1. LTCPR 12.2.2.2.c
The licensee shall ensure aesthetic, functional and surface integrity of the following are maintained: interior building components such as, but not limited to, partitions, ceilings, doors, casework, coatings and sealants.
2. HSCR 27(7), LTCPR 9.2.4.b
The licensee shall ensure fire drills are conducted a minimum of monthly in accordance with direction from the Office of the Fire Marshal.
3. LTCPR 9.2.2 c
The licensee shall ensure the Business Continuity Plan is reviewed a minimum of annually and revised as necessary to ensure it is current.
4. LTCPR 6.5.15
The licensee shall ensure the dining environment promotes residents' enjoyment, safety, comfort, independence and dignity, allowing them to socialize and to eat at a pace that suits them. There are ongoing opportunities to evaluate and improve the dining experience for the residents.
5. LTCPR 6.5.2.c
The licensee shall ensure the following processes are developed and followed: labeling of food in refrigerators and discarding of expired food.
6. LTCPR 6.5. 9
The licensee shall ensure supervision and assistance are provided during meals, snacks and other food related activities as necessary.
7. LTCPR 12.1.6
The licensee shall ensure hazardous products that may be harmful to residents are secured at all times and are not accessible to residents. They are stored and disposed of in accordance with established safety practices/manufacturers' recommendations.

8. HSCR 27(8), LTCPR 9.2.4.d, LTCPR 9.2.4.e
The licensee shall ensure fire protection equipment is maintained in good working order. Fire alarms and fire doors are tested monthly; fire extinguishers are inspected monthly and tested annually in accordance with the Office of the Fire Marshal. Records of testing and inspections of fire protection equipment and systems are maintained.