
Licensing Inspection Report (Semi-Annual Inspection)

Facility: VALLEY VIEW VILLA

Address: 6125 STELLARTON TRAFALGAR RD.
RIVERTON NS, B0K 1S0

Date(s) of Inspection: November 14, 2022

Requirements resulting from licensing inspection:

1. LTCPR 12.2.2.2.f
The licensee shall ensure aesthetic, functional and surface integrity of the following are maintained: all furnishings, equipment, exposed mechanical and electrical systems and components such as, but not limited to, fixtures, trim, devices, enclosures and fabrics.
2. LTCPR 12.1.6
The licensee shall ensure hazardous products that may be harmful to residents are secured at all times and are not accessible to residents. They are stored and disposed of in accordance with established safety practices/manufacturers' recommendations.