
Licensing Inspection Report (Semi-Annual Inspection)

Facility: NORTHWOODCARE BEDFORD INCORPORATED

Address: 123 GARY MARTIN DR.
BEDFORD NS, B4B 1G7

Date(s) of Inspection: October 3, 2022

Requirements resulting from licensing inspection:

1. LTCPR 12.2.2.2.c
The licensee shall ensure aesthetic, functional and surface integrity of the following are maintained: interior building components such as, but not limited to, partitions, ceilings, doors, casework, coatings and sealants.
2. LTCPR 12.1.6
The licensee shall ensure hazardous products that may be harmful to residents are secured at all times and are not accessible to residents. They are stored and disposed of in accordance with established safety practices/manufacturers' recommendations.