
Licensing Inspection Report (Semi-Annual Inspection)

Facility: NORTHSIDE GENERAL HOSPITAL

Address: 520 PURVES ST.
NORTH SYDNEY NS, B2A 1E3

Date(s) of Inspection: February 7, 2023

Requirements resulting from licensing inspection:

1. HSCR 21

It is a term and condition of every license that the licensee shall comply with the Acts and regulations, and any orders or directions of an appropriate authority, respecting fire, safety, health and sanitary requirements.